

Service Letters - Table of Contents

SL No	Issue	Date	Subject
00-002	10	2008-10-01	Islander Training Course Information - 2009
00-001	17	2016-12-21	Technical Publications User Guide
1	-	1974-02-01	Engine Mounting Frames - Weld Defects - Islander and Trislander
5	-	1977-10-10	Islander Elevators - Lead Missing From Mass Balance
7	-	1979-03-12	Rudder Bar Pillar Assembly
8	-	1979-05-04	Modification NB/M/911 Collins Autopilot. Minor Change to Elevator Trim System Pulley Guard
8	-	1979-09-13	Elevator Torque Tube (Trislander)
9	-	1979-09-28	Modification NB/M/911 Collins Autopilot. Change to the Aileron Servo Bridle Cables
10	-	1980-05-08	Omission of Radio Earth Links
11	-	1982-03-01	Incorporation of Two Mandatory Modifications NB/M/1161 and NB/M/1158
12	-	1983-11-01	Repositioning of BF Goodrich De-Icer Wire Harness
13	-	1985-02-08	Brake Pipe Chafe Wear Between Fairing Ribs and Brake Pipes on Aircraft with Leg Fairings to Modification NB/M/1059 Embodied
14	-	1985-07-25	Janitrol Aero Service Bulletin No. 75
15	-	1985-09-02	TGT Recommendations for Allison 250-B17C Engines
16	-	1985-12-05	Service and Periodic Maintenance of Rudder Cable System
17	-	1985-12-05	Notification of Availability of Repair Scheme or Modification in Respect of Wing Leading Edge Cracks
18	-	1986-09-29	Addition to Sliding Door - NB/M/1212
19	-	1986-11-18	Advance Information - Modification to Fairey Hydraulics Undercarriage
20	-	1987-05-20	Possible Incorrect Assembly of Flap Control Selector Switch on Pilot's Centre Pedestal
21	-	1987-05-22	Century Autopilot Installation
22	-	1987-11-01	Replacement of Passenger Upper Torso Inertia Reel (NB/M/1298)
23	-	1987-09-18	Century Autopilot Installation
24	-	1987-09-30	Recurrent Inspection of Allison 250-B17 Series Engines in Aircraft with Non-Beta Propeller Control Systems
25	-	1988-02-05	Century 31 Autopilot Installation
26	-	1988-02-05	APT-1-1000-150G Kulite Pressure Transducer
27	-	1988-03-11	Alterations to Sliding Door Assembly
28	-	1988-06-15	Century 31 Autopilot Installation
29	-	1988-06-24	Further Improvements to Sliding Door Assembly

SL No	Issue	Date	Subject
30	2	1989-01-04	C31 Autopilot - Removal of Electrical Trim Control Switch on Pilots Handwheel
31	-	1989-09-25	Century 31 Autopilot - Revised Flight Compartment Label and Flight Manual Supplement for Islanders with Subject Equipment
32	-	1990-03-01	Installation of J.B. Systems Air Conditioning to PBN Modification NB/M/1073
33	-	1990-03-01	Hartzell Propellers Fitted to IO-540 Engined Islanders
34	-	1990-04-27	Replacement of Central Annunciator Panel Part No. NB-80-1539 (Issues 1 or 2) by Part No. NB-80-1539 (Issue 3 or Later)
35	-	1991-01-16	Century 31 Autopilot - Reversal of Bolts on Pitch Servo Mounting Bracket
36	-	1991-09-25	Special Inspection of Bottom Guide Wheels in LH Rear Sliding Door Installations
37	2	1992-02-10	Change of External Supply Switch Circuit in 200 Amp Start/Generator Installations
38	-	1992-06-10	Revised Airspeed Limitations Placard for Islander C2230
39	-	1992-09-28	Improved Main Fuse Installation (F69 & F70) for Specific Turbine Islander Aircraft
40	1	1993-02-26	Century C2000 Autopilot Installation - Incorrect Roll Servo Drive
41	1	1993-02-26	FLIR 2000 System - Introduction of Warning Label to Operators Console
42	2	1993-04-28	Overheating of Bolt Attaching Fuse Between Shunt S1 and Link to Contactor RL87 at Installation of Shunts and Fuse for Air Conditioning Power Supply on Frame 46
43	1	1993-03-01	Possible Leakage of Pressure Transducers Models S122 Forms 1 and 8
44	-	1993-04-28	Engine Fuel and Control, Disarm N2 (Electronic) Overspeed Control System Multi-Engine Aircraft
45	1	1994-12-06	Defective Interior Trim Mouldings
46	1	1996-04-04	Rudder Trim Tab Flutter
47	1	2000-11-30	Flap Control Circuit
48	1	2001-07-01	Hartzell Service Letter HC-SL-61-189
49	1	2002-06-27	Engine Mounting Frames - Missing Drain Holes
50	1	2002-06-27	Use of Unapproved Parts in Islander Aircraft
51	1	2002-08-02	Change in CASA Rules for Aircraft Flight Manuals
52	1	2002-10-31	Cabin Floor Corrosion
53	-	-	Not Issued
54	1	2003-05-01	Improved Sliding Door Stop
55	1	2003-07-01	Recently Issued OEM Maintenance Information - June 2003
56	1	2004-01-12	Engine Exhaust Pipe Assemblies
57	1	2004-01-12	Classification of Service Bulletins
58	3	2013-04-15	Operator Feedback
59	2	2005-04-12	Recently Issued OEM Maintenance Information - May 2004

SL No	Issue	Date	Subject
60	1	2004-11-01	Islander Flight Manuals, Supplements and Modifications
61	1	2004-11-01	Recently Issued OEM Maintenance Information - November 2004
62	2	2005-07-18	Alternate Bearings
63	1	2005-04-12	Maintenance Information for the BN2T-4S Aircraft
64	2	2005-07-18	Recently Issued OEM Maintenance Information - April 2005
65	1	2006-11-27	Improved Accessibility for Elevator Control Rod Examination
66	1	2005-04-12	Structural Repair Approval Procedure
67	2	2005-11-07	Propellers - De-icer Boot Inspection
68	-	-	Not Issued
69	1	2005-07-18	Recently Issued OEM Maintenance Information - July 2005
70	1	2005-10-10	Recently Issued OEM Maintenance Information - October 2005
71	1	2005-10-10	Recently Issued Lycoming Service Bulletin and Airworthiness Directive
72	1	2006-03-01	Recently Issued OEM Maintenance Information - December 2005
73	1	2006-03-01	Generator Cable Loom - Examination
74	1	2006-03-01	Recently Issued Rolls-Royce Service Letter Warning of Engine Flameouts Due to Snow or Ice Ingestion
75	1	2006-03-01	Changes to the Hartzell Spinner Back Plate
76	1	2006-03-01	Propeller De-icing Pads Restraining Straps
77	1	2006-03-01	Engine Anti-ice Intake Heaters
78	1	2006-03-01	Servicing of Hartzell Propellers
79	1	2006-03-01	De-icing Fluid Approved for use on the Islander and Trislander Aircraft
80	1	2006-11-27	Recently Issued OEM Maintenance Information - October 2006
85	1	2007-07-16	Recently Issued OEM Maintenance Information - April 2007
86	1	2007-07-16	EASA Certification of Mode S Elementary and Enhanced Surveillance Transponder Modifications
87	1	2007-07-16	NARCO Avionics Inc. AT150 Transponder - Compliance with FAA AD 2004-08-16
89	1	2007-07-16	Lubrication of Hartzell Three Bladed Propellers
90	1	2007-07-16	FAA Airworthiness Directive 2006-24-07 (Hartzell Propellers)
91	1	2009-03-19	Hartzell Propeller Mounted Ice Protection Components, De-ice Boots, Anti-icing Boots, and Airframe Mounted Ice Protection System Components
92	1	2008-09-25	Recently Issued OEM Maintenance Information - September 2008
93	1	2009-02-24	Alternative 90 Degrees Opening Belt Buckle
94	1	2009-07-15	Compliance with EU Operations 1
95	1	2009-07-22	Information for Compliance with EU Operations 1



SL No	Issue	Date	Subject
96	1	2009-07-31	Introduction of Electronic Delivery of Information
97	2	2014-08-29	Special Instructions for Turbine Engined Aircraft Operating in Volcanic Ash
98	2	2014-08-29	Special Instructions for Piston Engined Aircraft Operating in Volcanic Ash
99	2	2010-06-24	Special Instructions for High Levels of Fuel System Icing Inhibitor (FSII) in Fuels
100	1	2010-12-23	Recently Issued OEM Maintenance Information - December 2010
101	1	2011-02-01	Incorrect Turret Bolts
102	1	2011-02-01	Insufficient Elevator Clearance
104	1	2011-02-01	Emergency Locator Transmitters
105	1	2011-06-01	Alternative Tyre Inner Tubes
108	1	2012-01-13	Alternative Pitot Static Heads
109	1	2011-12-22	SB 190 Page Count Check
110	1	2012-01-12	EASA Type Certificate Data Sheet
112	1	2012-06-26	Highlighting of Required AD Action for Kidde Graviner Hand Operated Fire Extinguisher
113	1	2012-09-11	Defective Standard Hardware - MS21042, NAS1291 and LN9338 Self-Locking Nuts and NAS626 Bolts
114	1	2012-11-30	Fuel Filler Cap Sealing
116	1	2013-04-15	Flight Control Surface - Bearings
120	1	2014-02-24	Resistance Check of Janitrol Heater Fuel Pump - P/N 71D31-1
121	1	2014-04-16	Cylinder Mounting Studs on Lycoming 540 Engines
123	1	2015-05-28	Flight Compartment Seat Locking Mechanism Inspections
124	1	2015-09-11	Greasing of Nose Wheel Steering Cables on Installation
126	2	2016-04-12	Autopilot Elevator Trim Cable
128	3	2016-08-12	Aileron Control Cable Twisting and Circuit Friction Testing
129	1	2106-04-12	Planned Introduction of Britten-Norman Master Minimum Equipment Lists